

Junction ISD Request for Estimates – Hail Damage Repairs

Junction ISD is accepting estimates for repairs that need to be done due to hail damage to JISD properties. Contact Ken Wimberley or Kyle Konz to make arrangements to view the properties needing repairs at 325-446-3510. Estimates must be submitted by July 19, 2021 at 1:00 pm to JISD Administration Building, 1700 College Street, Junction, Tx. or by email to ken.wimberley@junctionisd.net or kyle.konz@junctionisd.net

Roofing Request for Estimates

- #4 – Gym remove and replace metal gable trim
Remove and replace R panel metal walkway cover
- #8 – Kindergarten building – metal panel repairs
- #9 – Ag shop building – apply elastomeric coating to base flashings
- #13 – Remove and replace 3 tab composition shingle roofing
- #15 – Stadium restroom building – Remove and replace standing seam metal panels
Remove and replace ridge cap
Remove and replace pipe jacks
- #17 – Concessions building – remove and replace R-panel metal roofing
- #27 – Head start building – remove and replace 3 tab composition shingle roofing – steep roof elastomeric coating for modified roofs

Exterior Request for Estimates

- #1 – High school building – Remove and replace wall sconces on north elevation
- #2 – Elementary school – Remove and replace wall sconces on north elevation
- #4 – Remove and replace R panel walkway cover
- #11 – Band Hall – Remove and replace gable screen
- #12 – Life Skills portable building – Remove, replace and paint metal fascia
Remove and replace wall panel joint covers – 1 north, 2 west
Remove and replace window screens
- #13 – Distance learning portable building - Clean and prep railings and deck
Paint fascia, trim work, posts, and railings
Paint and prep materials
- #15 – Stadium restroom building – stain fencing, remove and replace louvered vents 1'-6" x 1"-6"
- #27 – Head start building – clean and prep fascia, trim work, posts and railings for paint, paint fascia, trim work, posts, railing, paint and prep materials

HVAC Request for Estimates

- #1 – High school building – comb condensing unit coils 8 total
- #4 – Gym – remove and replace HVAC sheet metal cover, comb coil/north unit, remove and replace unit screens 2' x 2'
- #12 – Life skills portable building – comb window unit coils
- #13 – Comb window unit coils - 1
- #14 – **Cafeteria freezer building**
Unit 1 Lennox – comb coil
Unit 3 Lennox – comb coil
Unit 5 – comb coil
Unit 6 – replace coil, remove and replace B-vent

Maintenance/transportation storage building #2 – comb window unit coil

Maintenance/transportation storage SHED – remove and replace north metal R panel wall